

## U. S. DEPT. OF THE INTERIOR OFFICE OF SURFACE MINING Mine Site Evaluation

State Program



Page 1 of Revised December 4, 1998

Month 3, 1847	tate 110	<u> </u>	Charles 1 at	VI GORD
1. Permittee/Person		9. Permit Number	V	10. Permit Type
CYPRUS PLATEAU MINING CORP.		UT-007-006		PP
2. Address		11. Field Visit Date	12. Purpose	13. SRA Present
847 NORTHWEST HIGHWAY 191		07/04/2005	0	Y
3. City	4. State	mm - dd - yyyy  14. Permit Status	15. Site Status	16. Facility Type
Helper	UT	A A	MC Status	BDEGK
5. Zip Code 6. Phone Nu	mber	17. OSM Office #	18. CCID#	19. Land Code
84526 (435) 472-0475		140	10. CCID #	SF
7. Operator Name, if Different than Permittee		20. M.S.H.A ID#	21. State Abrev.	22. County Name
		42-00171	UT	CARBON
8. Mine Name	,	23. AVS Permittee	<b>!</b>	24. State Office
STAR POINT MINE			Entity ID Number	24. State Office
		060102		
25. Hours 26. Signature	Block	١	27. Reviewing Off	icial:
1.0 a. Permit Review	, omilt	tulin	I hiltor	<u></u>
	Signature:	10/19/05	Signatur	re:
b. Site Visit Time	RY AUSTIN ID	# 116	D : D : [11] ,	101100
8.0 c. Travel Time	Printed Name:			18105 1d - yyyy
1.0 d. Report Writing Date: 08/	17/2005	7	Is Supplemental MSE	
1.0 d. Report Writing Date: 08/	1772005			
Permit Type — Item 10 IP = Interim Program, PP = Perma	anent Program, NP			
Purpose Type Codes Item 12 OxxOversight RFx	. Reclamation Fees	C	CRCitizen Complaint Re	itial site visit)
Axx Assistance Fxx	. Federal Actions	C	CF Citizen Complaint Fo	
Joint Inspection — Item 13 A joint inspection is when a star Permit Status — Item 14	AB Abando	ned: All surface and undi	erground coal mining activ	ities have ceased and
A Active: Coal mining and reclamation activities occurring or permitted but not yet disturbed.     INInactive (Permanent Program Permit): Phase II completed of Temporary Cessation of Operations. (Interim Program Permit): Coal mining completed and reclamation activities initiated.     BR Bond Release: Reclamation completed and State Regulator Authority (RA) has released all of the bond (Phase III Released).	operator 30 CFR AB1Bond For reclama mit) AB2Partially used to y AB3Reclaim	r has left the site without 840.11(g) orfeiture: Bond forfeiture tition in progress or not year Reclaimed Forfeiture: Freclaim site, but site not	completing reclamation as officially in process or com- t commenced. orfeited site where all bon- reclaimed to Program stan- site that has been reclaime	defined in npleted, and. ds have been dards.
Site Status Codes — Item 15		ining outlide an aita	NS Non-Site Visit: Stat FP Forfeiture Pending:	us of site not determined.
NDNo Disturbance: No coal mining and reclamation MCMin operations have been started.	regraded and await	nining activity on site, ling phase bond release. The RA has granted	actions to revoke th	ne permit, collect the s), and/or reclama-
have started and where coal mining operations ces	sation of mining pure (.131(b).	suant to 30 CFR 816/	tion of forfeited site FR. Forfeited and Recla	is in progress.
AP Active Coal Producing: Coal surface mining P1Pha	ise l'Rélease: At lea	ast Phase I bond release itted area. For interim	reclamation comple FO. Abandoned Site: A	eted. bandoned site that
AN Active Non-Producing: Active non-producing per facility such as tipple or preparation plant. P2 Pha	mits, partial bond re ise II Release: At le	iease. east Phase II bond releas	is permitted but the e WC Wildcat: Coal minin	g and reclamation
NMNo Mining: The Permit Status is active, site is not in Temporary Cessation, no surface coal P3Pha	he entire permitted ase III Release: Red RA has released all	clamation completed and	operations have or the activity is not co required permits fro	
Facility Type Codes — Item 16 A Surface DAncillary (Haulroad, Con E Refuse and/or Impoundr	veyor, and/or Rails)	HExploration Permit I Notice of Intent to	s L Explore	Remining site permitted under 30 CER785 25
B Underground F Loading Facility and/or T		.1 Exempt 16 and 2/3	S Iced Construction Exempti	RECEIVED
	Enforcemen		•	OCT 2 7 2005
Small Business Regulatory Your Co	Enforcements Are	it raiffiess Act Important	(SDKELA)	201 2 1 2003
The Small Business and Agriculture Regulatory Enforceme	nt Ombudsman and	d 10 Regional Fairness	Boards were established t	DHCOF OND BASSAMI

small businesses about Federal agency enforcement actions. The Ombudsman will annually evaluate the enforcement activities and rate each agency's

responsiveness to small business. If you are a small business (a business with 500 or fewer employees including those of affiliates) and wish to comment on the enforcement or compliance activities of OSM, call 1-888-REG-FAIR (1-888-734-3247).

## U. S. DEPT. OF THE INTERIOR OFFICE OF SURFACE MINING

**State Program** 

Mine Site Evaluation **Continuation Page** Permit Number UT-007-006 Field Visit Permittee/ Person 07/06/2005 CYPRUS PLATEAU Date

28. Performance Standard Categories Codes: 1=Compliance, 2=Noncompliance, 3=Not Planned, 4=Not Started, 5=Noncompliance Identified Elsewhere, 6=Previously Cited				
A. Administrative 1 Mining within Valid Permit 2 Mining within Bonded Area 31 Terms & Conditions of Permit 4 Liability Insurance 5 Ownership and Control 6 Temporary Cessation 7 AML Rec. Fees Non-Respondent 8 AML Rec. Fees Failure to Pay B. Hydrologic Balance 1 Drainage Control 2 Inspections & Certifications 3 Siltation Structures 4 Discharge Structures 5 Diversions 6 Effluent Limits 7 Ground Water Monitoring	D. Backfilling & Grading  11 Exposed Openings  2 Contemporaneous Reclamation  3 Approximate Original Contour  4 Highwall Elimination  5 Steep Slopes (includes downslope)  6 Handling of Acid & Toxic Materials  7 Stabilization (rills and gullies)  E. Excess Spoil Disposal  1 Placement  2 Drainage Control  3 Surface Stabilization  4 Inspections & Certifications  F. Coal Mine Waste  (Refuse Piles/Impoundments)  1 Drainage Control  2 Surface Stabilization	H Subsidence Control Plan  I. Roads  1 Road Construction  2 Certification  3 Drainage  4 Surfacing and Maintenance  5 Reclamation  J. Signs & Markers  1 Signs  2 Markers  K Distance Prohibitions  L. Revegetation  1 Vegetative Cover  2 Timing  M Postmining Land Use  N. Other		
C. Topsoil & Subsoil  1 Removal  2 Substitute Materials  3 Storage and Protection  4. Redistribution	4 Inspections and Certifications 5 Impounding Structures Catagor G. Use Of Explosives 1 Blaster Certification 2 Distance Prohibitions 3 Blast Survey/Schedule 4 Warnings & Records 5 Control of Adverse Effects  Performs Catagor  H  Catagor  Annual Certification  Performs Catagor  Annual Certification  Annual Certification  Annual Certification  Catagor  Annual Certification  Control Certification  Control Certification  Annual Certification  Control Certification  Certification  Certification  Certification  Certi			
Performance Standard Catago 30 CFR Counterpart  A. Administrative	1. Placement			
B. Hydrologic Balance	Street			
D. Backfilling & Grading	(816/817.95-107) 14, 15, & 823.11 & 21 L. 102(a)(1) 102(a)(2) 107 108 109 109 109 109 109 109 109 109 109 109			

October 19, 2005 Plateau Mining Corp. 847 Northwest Highway 191 Helper, UT 84526

Star Point Mine Subsidence evaluation July 7, 2005

Participants:

Dennis Ware, Plateau Mining Corp. (PMC)
Susan White, Utah Division of Oil, Gas and Mining (DOGM), DOGM staff members
Dana Dean, Jeri Ann Ernsten, Wayne Hedberg, Wayne Western, Jim Smith, Dave Darby, Steve
Fluke, and Steve Christiansen
Henry Austin & Howard Strand, Office of Surface Mining (OSM)

The above participated in a special focus evaluation for 2005 regarding mining beneath perennial streams. The north fork of the right fork of Miller Creek was selected for evaluation by the joint DOGM / OSM Evaluation Team. This perennial stream has been studied in the past by USGS and BLM staff to document the affects of longwall mining subsidence on the stream. Inspection participants understood the BLM is again conducting studies of this stream.

Our topic was intended to evaluate the subsidence effects to the stream and determine whether they have caused material damage outside the permit area, adversely affected state-appropriated water supplies, and that the subsidence effects were mitigated (if necessary or possible) as required in the approved DOGM mining permit.

The primary purpose of this field evaluation was to make general observations of the obvious subsidence zone that has affected the north fork of the right fork of Miller Creek. We walked down slope from the headwaters area to below the known subsidence zone in the north fork. The reach of stream affected is several hundred feet long, and the stream is no longer visible in the surface channel, presumably it is flowing in the stream channel alluvium beneath the surface. We did see evidence of the stream flow resurfacing in the stream channel below this known zone of subsidence influence. We saw evidence of rock (sandstone outcrops) spalling, and minor ground movement in several areas associated with the known subsidence zone. Surface (ground) effects were hard to determine due to vegetation density and steep slopes.

I used my personal GPS unit and captured point locations of various points of interest along the subsidence zone. These point location readings were given to Dave Darby during the evaluation. (Subsequent to the evaluation I lost my field book and it has not been recovered to date.) Inspection participants discussed the surface water monitoring record here. It was not clear during the evaluation what effects, if any, have been documented with respect to diminished total flow through the subsidence zone and resultant affects downstream. We also did not determine whether diminished flows in the known subsidence zone have or are currently affecting state appropriated water supplies. The evaluation team will continue to evaluate the subsidence effects to this stream.

Address any question on this report to Henry Austin, OSM, at (303) 844-1400 x1466.